

Silicon Graphics® Octane® Workstation
VPro™ Graphics
Power Supply Upgrade Instructions

Document Number 007-4208-001

CONTRIBUTORS

Written by Alan Stein

Production by Glen Traefald

Illustrated by Kwong Liew and Dan Young

Engineering contributions by Ron Berthiaume, Lauro Manalac, Mark Heuchert,
Manuel Arreola, Bob Sanders, Natalia Gabrea, Tom Shou, Jesse Barker, Jim Miller,
Dale Ah Tye, and many others on the VPro graphics Engineering and Business
Team

© 2000, Silicon Graphics, Inc.— All Rights Reserved

The contents of this document may not be copied or duplicated in any form, in whole
or in part, without the prior written permission of Silicon Graphics, Inc.

LIMITED AND RESTRICTED RIGHTS LEGEND

Use, duplication, or disclosure by the Government is subject to restrictions as set
forth in the Rights in Data clause at FAR 52.227-14 and/or in similar or successor
clauses in the FAR, or in the DOD, DOE or NASA FAR Supplements. Unpublished
rights reserved under the Copyright Laws of the United States.

Contractor/manufacturer is Silicon Graphics, Inc., 1600 Amphitheatre Pkwy.,
Mountain View, CA 94043-1351.

For regulatory and compliance information, see your *Octane Workstation Owner's
Guide*.

Silicon Graphics and Octane are registered trademarks, and SGI the SGI logo, and
VPro are trademarks of Silicon Graphics, Inc.

Silicon Graphics® Octane® Workstation VPro™ Graphics Power Supply Upgrade
Instructions
Document Number 007-4208-001

Contents

List of Figures v

**Silicon Graphics® Octane® VPro™ Graphics
Power Supply Upgrade Instructions** 1

Preparing Your Workstation 2

Removing the PCI Module 4

Removing the Power Supply 7

Replacing the Power Supply 9

Reinstalling the PCI Module 11

Verifying the Power Supply Upgrade 14

List of Figures

Figure 1	Powering Off the Octane Workstation	2
Figure 2	Unplugging the Power Cable	3
Figure 3	Removing the Cables from the PCI Module	4
Figure 4	Loosening the PCI Module Screws	5
Figure 5	Pulling the PCI Module Release Lever	5
Figure 6	Removing the PCI Module	6
Figure 7	Identifying the Compression Connector on the PCI Module	6
Figure 8	Placing a Cap on the PCI Module Compression Connector	7
Figure 9	Loosening the Power Supply Screws	8
Figure 10	Pulling the Power Supply from the Octane Workstation	8
Figure 11	Plugging In the Power Cable	9
Figure 12	Sliding In the New Power Supply	9
Figure 13	Tightening the Power Supply Screws	10
Figure 14	Removing the Cap from the PCI Module Compression Connector	11
Figure 15	Inserting the PCI Module	11
Figure 16	Closing the PCI Module Release Lever	12
Figure 17	Tightening the PCI Module Screws	12
Figure 18	Reconnecting the PCI Cables	13
Figure 19	Hardware Inventory List	14

Silicon Graphics® Octane® VPro™ Graphics Power Supply Upgrade Instructions

This guide explains how to upgrade your Octane power supply for VPro graphics.

Caution: You must install your new power supply before you perform the VPro graphics upgrade.

This guide shows you how to remove your current power supply and install the required replacement for VPro graphics. The Octane power supply is located at the bottom of your workstation and you do not have to open the chassis to remove it. If your workstation has a PCI module installed, you have to remove it before you can upgrade your power supply.

The following topics are covered:

- “Preparing Your Workstation” on page 2
- “Removing the PCI Module” on page 4
- “Removing the Power Supply” on page 7
- “Replacing the Power Supply” on page 9
- “Reinstalling the PCI Module” on page 11
- “Verifying the Power Supply Upgrade” on page 14

Preparing Your Workstation

1. Open the cover and push the power button (See A in Figure 1) to power off your workstation.
2. Unplug the power cable (B) from the electrical socket.
3. Press the monitor power switch (C) to power off your monitor.




Figure 1 Powering Off the Octane Workstation

4. Unplug the power cable from the back of your workstation (power supply), as shown in Figure 2.

Before you proceed to the next section, wait until the power supply fan stops spinning and you cannot feel any air coming out of the power supply.




Figure 2 Unplugging the Power Cable

Removing the PCI Module

If a PCI module is not installed in your workstation, skip to the next section and follow the instructions for removing your power supply.

If a PCI module is installed in your workstation, you must remove it before you can remove the power supply. Follow the directions below to remove the PCI module, and then see the next section to upgrade your power supply.

Caution: The components inside your workstation are extremely sensitive to static electricity; you must wear the wrist strap while removing and reinstalling the PCI module.

1. Attach the wrist strap.
 - Unroll the first two folds of the band.
 - Wrap the exposed adhesive side firmly around your wrist, unroll the rest of the band, then peel the liner from the copper foil at the opposite end.
 - Attach the copper foil to any exposed electrical ground, such as a metal part of your workstation.
2. Remove any cables from the PCI module, as shown in Figure 3.




Figure 3 Removing the Cables from the PCI Module

3. Loosen the two captive screws that secure the PCI module to the workstation until they are disconnected from the chassis, as shown in Figure 4.




Figure 4 Loosening the PCI Module Screws

4. Pull the release lever toward you and to the right, as shown in Figure 5.




Figure 5 Pulling the PCI Module Release Lever

5. Remove the PCI module by sliding it out of the workstation, as shown in Figure 6, then place it on a dry, antistatic surface, such as your desktop.




Figure 6 Removing the PCI Module

Caution: The compression connector on the back of the PCI module is delicate and easily damaged. Do not touch or bump the gold area of the compression connector (see Figure 7). For more information about compression connectors, see Appendix B in your *Octane Owner's Guide*.




Figure 7 Identifying the Compression Connector on the PCI Module

6. Place a cap on the compression connector on the back of the PCI module, as shown in Figure 8. (Compression connector caps are included with the workstation.)




Figure 8 Placing a Cap on the PCI Module Compression Connector

Removing the Power Supply

If you did not power off your workstation, unplug the power cable from the electrical outlet and your workstation, and power off your monitor, do it now. You do not have to wear the wrist strap to remove the power supply.



Warning: Make sure the power cable is disconnected from the electrical socket and your workstation (power supply) before you begin this procedure.

1. Locate the two captive screws near the bottom of the power supply that secure it to the chassis.
2. Using a Phillips screwdriver, loosen the captive screws until they release from the chassis, as shown in Figure 9.




Figure 9 Loosening the Power Supply Screws

3. Grasp the handle and pull the power supply from the chassis, as shown in Figure 10.




Figure 10 Pulling the Power Supply from the Octane Workstation

Replacing the Power Supply

Follow these steps to install the new power supply:

1. Tilt the new power supply upward and plug in the power cable, as shown in Figure 11.




Figure 11 Plugging In the Power Cable

2. Slide the new power supply into your workstation, as shown in Figure 12.
3. Push on the power supply to firmly connect it to the frontplane.

Note: Be sure the tabs (holding the screws) on the power supply are flush with the chassis.




Figure 12 Sliding In the New Power Supply

4. Tighten the screws that attach the power supply to the workstation, as shown in Figure 13.




Figure 13 Tightening the Power Supply Screws

You are finished installing the new power supply.

If you removed the PCI module, reinstall it now by following the instructions in the next section.

If you are not reinstalling the PCI module, plug the power cable into an electrical outlet, press the power button on your workstation and then press the power switch on your monitor.

Note: You can verify the power supply upgrade by following the instructions on page 14.

Reinstalling the PCI Module

1. Remove the cap from the compression connector on the back of the PCI module, as shown in Figure 14, and save it for future use.




Figure 14 Removing the Cap from the PCI Module Compression Connector

2. Insert the PCI module into your workstation, as shown in Figure 15, and then push it until the tabs are flush with the chassis.




Figure 15 Inserting the PCI Module

3. Close the release lever by pushing it to the left until it is parallel with the PCI module, as shown in Figure 16.




Figure 16 Closing the PCI Module Release Lever

4. Tighten the captive screws that secure the PCI module to the workstation, as shown in Figure 17.




Figure 17 Tightening the PCI Module Screws

5. Reconnect any PCI cables to the PCI connectors, as shown in Figure 18.




Figure 18 Reconnecting the PCI Cables

6. Plug the power cable into an electrical outlet, press the power button on your workstation, and then press the power switch on your monitor.
7. Remove the wrist strap.

You are finished upgrading your power supply for VPro graphics.

See the next section to verify your power supply upgrade.

Verifying the Power Supply Upgrade

1. Check your power supply by entering `hinv -m` in a command line window. The hardware inventory list appears, as shown in the example in Figure 19.




Figure 19 Hardware Inventory List

2. Verify the following information in the third line of the hardware inventory list:
The part number for `PWR.SPPLY.ER` must be: `060-0035-00x` or later, where $x = 1$ or higher, as shown in the example in Figure 19.
If the correct part number is displayed, begin the VPro graphics upgrade, as described in your *Octane Workstation VPro Graphics Upgrade Kit Installation Guide*.
If the correct part number is not displayed for `PWR.SPPLY.ER`, contact your authorized SGI sales representative.